FOID * State * Incident Date *	YYYY 2017 53 Delete NFIRS - Station Incident Number Exposure Exposure Basic
X Street address Intersection In front of Number/Milepost Prefix	IETTA GA 30060 -
Directions	State Zip Code
Cross street or direct line transfer Type *	E1 Date & Times Midnight is 0000 E2 Shift & Alarms
Aid Giron	dates are the Month Day Year Hr Min Sec Local Option same as ALARM slways required Date.
Mutual aid received Automatic aid recv. Mutual aid given Automatic aid given Other aid given Their FDID Their State Their FDID Their State Their FDID Their State Incident Number	ARRIVAL required, unless canceled or did not arrive Arrival * 02 26 2017 12:33:54 Shift or Alarms District Arrival * 02 26 2017 12:39:34 CONTROLLED Optional, Except for wildland fires Controlled LAST UNIT CLEARED, required except for wildland fires Local Option
Actions Taken *	Cleared 02 26 2017 15:32:28 Special Study ID# Special Study Value
Primary Action Taken (1) 12 Salvage & overhaul Additional Action Taken (2) Additional Action Taken (3)	G1 Resources * Check this box and skip this section if an Apparatus or Personnel form is used. Apparatus Personnel Suppression 0010 0024 EMS Check this box and skip this section if an Apparatus or Personnel for non fires. LOSSES: Required for all fires if known. Optional for non fires. None Property \$, 080, 000 Contents \$, 008, 000 Contents \$ PRE-INCIDENT VALUE: Optional
	Check box if resource counts include aid received resources.
Completed Modules X Fire-2 Deaths Ing Structure-3 Civil Fire Cas4 Fire Serv. Cas5 EMS-6 HazMat-7 Wildland Fire-8 X Apparatus-9 X Personnel-10 X Arson-11 Property Use* Structures	Mixed Use Property Mixed Use Property
131 Church, place of worship 161 Restaurant or cafeteria 162 Bar/Tavern or nightclub 213 Elementary school or kindergarter 215 High school or junior high 241 College, adult education 311 Care facility for the aged 331 Hospital Outside	449 Commercial hotel or motel 459 Residential, board and care 464 Dormitory/barracks 519 Food and beverage sales 629 Laboratory/science lab 700 Manufacturing plant 819 Livestock/poultry storage(barn) 882 Non-residential parking garage 891 Warehouse
124 Playground or park 655 Crops or orchard 669 Forest (timberland) 807 Outdoor storage area 919 Dump or sanitary landfill 931 Open land or field	938 Graded/care for plot of land 946 Lake, river, stream 951 Railroad right of way 960 Other street 961 Highway/divided highway 962 Residential street/driveway 981 Construction site 984 Industrial plant yard 986 Industrial plant yard 100xup and enter a Property Use code only if 961 Property Use layer 962 Multifamily dwelling

Cases, Trian and Trian a	serson/Ent-	ty Involved
Secretary States Secretary	Local Option	and the same of th
No. Content	D Charles	Area Code Phone Number
The first order of the set of the	Same address as	Mr., Ms., Mrs. Pirst Name
The state of the sea o	Then skip the three	MI Last Name Suffix
MONE paople involved Check this box and ettach Supplemental Forms (MFIRS-15) as Decessary More paople involved Check this box and ettach Supplemental Forms (MFIRS-15) as Decessary More paople involved Check this box and ettach Supplemental Forms (MFIRS-15) as Decessary More paople involved Check this box and ettach Supplemental Forms (MFIRS-15) as Decessary More part	lines. address	
Sal Office has Special Color Special Col		Sileet type Suffix
CAR 30060 -		Post Office Box
State Stat		GA 30060 -
Level Option Chees State Poor Mer. Mar. Mer. Mar. Mar.	More people in	State Zip Code
Level Option Chees State Note: The Test of This rection Deathers nome its Applicable Aces Code Thomas Number	V.	Torself Check this box and attach Supplemental Forms (NFIRS-1S) as necessary
Check this box of the Market Name (If Applicable) Check this box of the Market Name (If Applicable) Check this box of the Market Name (If Applicable) Check this box of the Market Name (If Applicable) Check this box of the Market Name (If Applicable) Check this box of the Market Name (If Applicable) Description (Included Complete) First Name First Name First Name Description (Included Engines 51, 52, 54, truck 51, 52 rescue 51, aguad 52 and air 54 . E53 arrived on the first floor impinging on the deck above and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 preconceat. E53 crew began fire attack from the exterior removing what was left of window and regan extinguishment. E53 knocked down the bulk of fire resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQS2 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 orew extinguished the rest of the fire and salvage and overhaul was begun. E53 orew extinguished the rest of the fire and salvage and overhaul was begun to S53 and the extracture which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 orew extinguished the rest of the fire and salvage and overhaul was begun to S53 and the extracture of S53 officer material to the salvage of the salvage of the salvage of the salvage of the s	Same a	s person involved?
Check this boy if same address as the state of the state	Local Option The re	of this section.
The match the softess states and regions to the first street of Highway Lest Name First Street of Highway Street First Street of Highway		Area Code Phone Number
The marks are some to find a three story residential condominum with fire showing from a bay window on the first floor impinging on the dock show and to the Delta side. E53 reported heavy fire removing what was left of window and longon extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly apir. Before making entry E53 asks with the other orthogone. E53 orthogone was inside and resident stated negative on other occupants. At this time other ocquipment began arriving on scene. E53 entered the subject stated a line needed. E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguishment E53 officer met which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhald was begun. E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhald was begun. E53 crew exted structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. Sol released equipment as necessary with exception of 53 and on shift investigation. Both units returned to service. **Lauthorization** **Lauthorization	Check this how is	
TREMER'S State Street or Highway Post Officer Book Treeties Street or Highway Post Officer Book Remarks Local Option E53 responded to report of commercial fire along with a full commercial response which included Engines S1, 52, 54, truck 51, 52 rescue 51, squad 52 and air 54 . E53 arrived on scene to find a three story residential condominum with fire showing from a bay window on the first floor impinging on the deck shows and to the Delta side. E53 reported heavy fire removing what was left of window and tagan extinguishment. E53 crew began fire attack from the exterior removing what was left of window and tagan extinguishment. E53 knocked down the bulk of fire resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. Soll released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization E Authorization Fosticer Member making report 10 Signature	incident location	MI Last Name
L Remarks	duplicate address	Markey
L Remarks Local Options E53 responded to report of commercial fire along with a full commercial response which included Engines 51, 52, 54, truck 51, 52 rescue 51, squad 52 and air 54. E53 arrived on the first floor impinging on the deck show and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 precented. E53 crew began fire attack from the exterior removing what was left of window and tegan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from S052 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 orew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew extinguished access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. Soll released equipment as necessary with exception of 53 and on shift investigation. Both units returned to service. L Authorization Officer in charge ID Signature Position of tank Assignment Month Day Test	lines.	
L Remarks Local Option E53 responded to report of commercial fire along with a full commercial response which included Engines 51, 52, 54, truck 51, 52 rescue 51, squad 52 and air 54. E53 arrived on the first floor impinging on the deck showe and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 precentect. E53 crew began fire attack from the exterior removing what was left of window and twom extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked enter equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from 8052 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure. E53 officer met with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 orew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. S01 released equipment as necessary with exception of 53 and on shift investigator. E63 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization Position of tank Assignment Month Day Test		Post Office Box Apt./Suite/Room
Remarks Local Option E53 responded to report of commercial fire along with a full commercial response which included Engines 51, 52, 54, truck 51, 52 rescue 51, squad 52 and air 54. E53 arrived on scene to find a three story residential condominium with fire showing from a bay window on the first floor impinging on the deck above and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 preconnect. E53 crew began fire attack from the exterior removing what was left of window and twgan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entred structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time 253 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. Soll released equipment as necessary with exception of 53 and on shift investigation. Both units returned to service. **Position or rank** Assignment** Month Day Test**		L -
Es3 responded to report of commercial fire along with a full commercial response which included Engines 51, 52, 54, truck 51, 52 rescue 51, squad 52 and air 54. E53 arrived on scene to find a three story residential condominium with fire showing from a bay window on the first floor impinging on the deck above and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 preconnect. E53 crew began fire attack from the exterior removing what was left of window and togan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. S01 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **Lauthorization** **Lauthorization		State Zip Code
E53 responded to report of commercial fire along with a full commercial response which included Engines 51, 52, 54, truck 51, 52 rescue 51, squad 52 and air 54. E53 arrived on scene to find a three story residential condominium with fire showing from a bay window on the first floor impinging on the deck above and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 preconcet. E53 crew began fire attack from the exterior removing what was left of window and kegan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew extited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization		
scene to find a three story residential condominium with fire showing from a bay window on the first floor impinging on the deck above and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 preconnect. E53 crew began fire attack from the exterior removing what was left of window and tegan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from S052 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew extired structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **L Authorization**		10 report of
scene to find a three story residential condominium with fire showing from a bay window on the first floor impinging on the deck above and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 preconnect. E53 crew began fire attack from the exterior removing what was left of window and tegan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew extited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **L Authorization** **L Authorization** **Left Member making report ID** **Signature** **Position or rank** **Assignment** **Assignment** **Nonta 54, Yest** **Position or rank** **Assignment** **Nonta 54, Yest** **Position or rank** **Assignment** **Double Signature** **Left Member making report ID** **Signature** **Position or rank** **Assignment** **Double Signature** **Posit	included Engine	o report of commercial fire along with a full commercial response which
the first floor impinging on the deck above and to the Delta side. E53 reported heavy fire and smoke and pulled an 1 3/4 preconsect. E53 crew began fire attack from the exterior removing what was left of window and togan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **Description of tank** Assignment** Month Day Year** Year** The Signature of Signature		
removing what was left of window and tegan extinguishment. E53 knocked down the bulk of fire and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. S01 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **Position of rank** Assignment Month Day Year Total Conference of the making report ID Signature Position of rank Assignment Month Day Year Total Conference of the making report ID Signature Position of rank Assignment Month Day Year Total Conference of the making report ID Signature Position of rank Assignment Month Day Year Total Conference of the making report ID Signature Position of rank Assignment Day Year Total Conference of the making report ID Signature Position of rank Assignment Day Year Total Conference of the making report ID Day Year Total Conference of the making report ID Day Year Total Conference of the making report ID Day Year Total Conferen	the first floor	impinging on the deck shows and to the R live showing from a bay window on
and approached the front door which was slightly ajar. Before making entry E53 asked resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **Position of rank** Assignment** Month Day Teat** **Position of rank** Assignment** **Position of rank** Assignment** **Position of rank** Assignment** **Position of rank** **P		
resident if anyone was inside and resident stated negative on other occupants. At this time other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization O3	A CONTRACTOR OF THE PROPERTY OF THE PROPERTY OF THE	THE TOTAL OF WINDOW MIND COORD AVELDANIS SAMONE DEC LANGE J.
other equipment began arriving on scene. E53 entered structure and began extinguishment from the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. Authorization		The first door willing was Silder V alar Before making onto.
the interior entryway. A crew member from SQ52 approached E53 and asked what assistance was needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **Lauthorization** Officer in charge ID** Signature** Position or rank** Assignment** Month Day Year Teat of rank** Month	TI UII	your was inside and resident stated negative on other occupants at the
needed. E53 officer stated a line needed to be taken to second floor to check for extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 orew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. Authorization	course eduthmen	began arriving on scene. Edd entered structure and began extinguishment from
Extension. Also around this time E53 officer's radio was having difficulty transmitting and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. **Desition of rank** Assignment** Month Day Year Nonth Day Year Sofficer Member making report ID** Signature** **Position of rank** Assignment** Month Day Year Sofficer Member making report ID** Signature** **Position of rank** Assignment** Month Day Year Sofficer Member making report ID** Signature** **Position of rank** Assignment** Month Day Year Sofficer Member making report ID** Signature**	rue Turettor el	icryway . A crew member from SQ52 approached E53 and asked what assistance was
and no additional reports were made by E53. 501 was on scene and took command and began assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization O3	needed. E33 of	Ilicer stated a line needed to be taken to second floor to check for
assigning units (See other unit narratives). E53 entered the structure which was filled with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization Officer in charge ID Signature Position or rank Assignment Honth Day Year Os if Sofficer Member making report ID Signature Position or rank Assignment Honth Day Year	extension. Als	30 around this time E53 officer's radio was having difficulty transmitting
with trash and debris. Water supply was established at E53. E53 crew extinguished the rest of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found. S01 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization O3	and no addition	reports were made by E53. 501 was on scene and took command and began
of the fire and salvage and overhaul was begun. E53 crew exited structure. E53 officer met with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization O3	with trach and	debric Water supply was established at 553 PF3
with 501 and gave face to face update. E53 was assigned to overhaul and gained access to delta side apartment #853 and removed some ceiling and wall to check for extension with none found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization Officer in charge ID Signature Position or rank Assignment Month Day Year of the ck of the charge ID Signature Position or rank Assignment Month Day Year Year of the ck of the charge ID Signature Position or rank Assignment Month Day Year Year on the ck of the charge ID Signature Position or rank Assignment Month Day Year Year on the ck of the charge ID Signature Position or rank Assignment Month Day Year Year on the charge ID Signature Position or rank Assignment Month Day Year Year of the charge ID Signature Position or rank Assignment Month Day Year Year Month Day Year Year Month Day Year North Day Ye	of the fire and	salvage and overhaul was begun F53 crew exited structure F53 officer bet
delta side apartment #853 and removed some ceiling and wall to check for extension with none found. 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization Officer in charge ID Signature Position or tank Assignment Month Day Year Officer in charge ID Signature Position or tank Assignment Month Day Year Position or tank Assignment Month Day Year Position or tank Assignment Month Day Year		
found 501 released equipment as necessary with exception of 53 and on shift investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization Officer in charge ID Signature Position or rank Assignment Month Day Year Check Ox if Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year		
investigator. E53 checked for hotspots with none found. On duty investigator completed investigation. Both units returned to service. L Authorization Officer in charge ID Signature Position or rank Assignment Month Day Year Check ox if Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year		
L Authorization Officer in charge ID Signature Position or rank Assignment Month Day Year Officer Member making report ID Signature Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year		
Officer in charge ID Signature Position or rank Assignment Month Day Year Theck lox if X and and an Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year	investigation.	Both units returned to service.
Officer in charge ID Signature Position or rank Assignment Month Day Year Theck lox if X and and an Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year	40	
Officer in charge ID Signature Position or rank Assignment Month Day Year Theck lox if X and and an Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year		
Officer in charge ID Signature Position or rank Assignment Month Day Year Theck lox if X and and an Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year		
Officer in charge ID Signature Position or rank Assignment Month Day Year Theck lox if X and and an Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year		
Officer in charge ID Signature Position or rank Assignment Month Day Year Theck lox if X and and an Assignment Month Day Year Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year		
Officer in charge ID Signature Position or rank Assignment Month Day Year Od Ol 2017 Year On the Ck Ox if X Assignment Month Day Year Position or rank Assignment Month Day Year		
Officer in charge ID Signature Position or rank Assignment Month Day Year O3 O1 2017 O3 O1 2017 Position or rank Assignment Month Day Year Position or rank Assignment Month Day Year	L Authorization	
Officer in charge ID Signature Position of fank Assignment O3 O1 2017 Oane Member making report ID Signature Position or rank Assignment Month Day Year	T.	
theck ox if X ame so Officer Member making report ID Signature Position or rank Assignment Month Day Year	Officer in cha	Position of Tank Assignment
theck ox if X ox if X Position or rank Assignment Month Day Year ame s Officer Member making report ID Signature	Officer in cus	
ox if X ame Position or rank Assignment Month Day Year so Officer Member making report ID Signature	Check F	
s Officer Member meaning report in	Box if X	Don't lon or fatt ASSIGNMENT TO
n Chatye.	as Officer Member making : in charge.	Share in ardunears

.